

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2020

Submitted Date:

11/10/2020

Document Number:

688800817

FIELD INSPECTION FORM

Loc ID 325665 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Heil, John		john.heil@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215195	WELL	PR	04/25/2018	GW	067-06800	BEUTEN A 1	EI
474317	Domestic Tap	AC	03/26/2020		-	Domestic Tap 29NENE	EI

General Comment:

On November 6, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Beuten A #1. For the most recent field inspection report of this facility, please refer to document #693902144.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign located near location entrance. API # on location sign is inaccurate. Simcoe LLC listed as the operator.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location sign.		Date:
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Exhaust hoses left near pump controller.		
Corrective Action:	Comply with Rule 603.f.		Date: 11/24/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Stained soil near concrete pad for pump jack beneath prime mover.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 12/10/2020
Produced Water	WELLHEAD	<= 1 bbl	
Comment:	Well head and surrounding gravel are stained and wet.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 12/10/2020
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Partial sound walls on north and east sides of pump jack. Guard fencing present.		
Corrective Action:			Date:
Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		

Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Domestic tap.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 215195 Type: WELL API Number: 067-06800 Status: PR Insp. Status: EI

Facility ID: 474317 Type: Domestic Tap API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	"Trapper" stuffing box secondary containment.
		Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On November 6, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Beuten A #1. For the most recent field inspection report of this facility, please refer to document #693902144.</p> <p>During this inspection stained soil was observed alongside the concrete pad for the pump jack, and around the well head.</p> <p>Unused exhaust hoses have been left inside the sound walls.</p>	hughesjo	11/10/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800818	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5288620