

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2020

Submitted Date:

11/10/2020

Document Number:

688308946**FIELD INSPECTION FORM**Loc ID 477611 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10720Name of Operator: KODA EXPLORATION LLCAddress: 11799 WEST 18TH AVENUECity: LAKEWOOD State: CO Zip: 80215**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sullivan, Ryan	720 244 8049	rsullivantc@gmail.com	
Elgerd, Anders	3039152555	elgerd@comcast.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477612	WELL	XX	08/10/2020		073-06776	WHP Misty 2-7	DG

General Comment:[Surface Spud/Cementing Inspection](#)

Inspected FacilitiesFacility ID: 477612 Type: WELL API Number: 073-06776 Status: XX Insp. Status: DG**Well Drilling**

Rig: Rig Name: Schaal Rig 5 Pusher/Rig Manager: Armando
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: NO Unlined Pit: YES Closed Loop: NO Semi-Closed Loop: NO
 Multi-Well: NO Disposal Location: on location

Comment: 11/6/2020
TD 487
Pipe set @ 486.5'
elogged by COLOG wireline found no water

Corrective Action: _____ Date: _____

Cement**Cement Contractor**

Contractor Name: HSI Contractor Phone: _____

Surface Casing

Cement Volume (sx): 195 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____
 Good Return During Job: _____ Cement Type: _____

Comment: 11/6/2020
Class G, 2% CaCl, 3% Gel, 15.8 ppg

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Slope Roughening	Pass					
Ditches	Pass					
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Drilling PitLined: NOPit ID: Lat: Long: Reference Point: Other: Length: 103Width: 138**Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688308991	Koda Exploration WHP Misty 2-7 Surface Spud	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5289013