

Inspection Photos
Operator: BP America
API: 067-05312
Date: 11/13/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with sagebrush and rubber rabbitbrush.




Photo 3. View of erosional channel in the central project area from upper well pad to lower well pad, needs stabilization.



Photo 4. View of the eastern project area from the southeastern corner facing northward.



Photo 5. View of reference area comprised of sagebrush shrubland with purple threeawn, James galleta, thickspike wheatgrass, and prickly pear.