

Inspection Photos
Operator: Rim Operating
API: 067-08071
Date: 11/13/2020



Photo 1. View of the project area from the northeastern corner facing center. Revegetation is progressing with grasses and shrubs such as thickspike wheatgrass, rubber rabbitbrush, and purple threeawn.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of reference area comprised of sagebrush shrubland with understory of James galleta, purple threeawn, Arizona gumweed, snakeweed, and prickly pear.