

Inspection Photos

Location Name: LARAMIE ENERGY LLC Currier /26-15 Pad

Location ID: 334528



Photo #2246 from entrance to location.



Photo #2247 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Currier /26-15 Pad

Location ID: 334528



Photo #2250 Sediment migrating off of location and on to access road due to tracking.



Photo #2251 Sediment migrating off of location and on to access road due to tracking.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Currier /26-15 Pad

Location ID: 334528




Photo #2252 Tracking at entrance to location



Photo #2253 Tracking at entrance to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Currier /26-15 Pad

Location ID: 334528



Photo #2254 Access road.