

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2020

Submitted Date:

11/16/2020

Document Number:

699802106

FIELD INSPECTION FORM

Loc ID: 334528 Inspector Name: De Paolo, Corey On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285683	WELL	PR	11/03/2015	GW	077-09095	CURRIER 26-15	PR
285684	WELL	PR	08/31/2012	GW	077-09096	CURRIER 26-16	PR
285685	WELL	PR	05/01/2020	GW	077-09097	CURRIER 26-14	PR
285687	WELL	PR	03/01/2017	GW	077-09098	CURRIER 26-10	PR
285688	WELL	PR	05/30/2012	GW	077-09099	CURRIER 26-9C	PR
285692	WELL	PR	04/10/2015	GW	077-09100	CURRIER 35-2	PR
285694	WELL	PR	01/01/2011	GW	077-09101	CURRIER 35-1	PR
285696	WELL	PR	11/03/2015	GW	077-09102	CURRIER 25-13	PR
285699	WELL	SI	07/01/2020	GW	077-09103	CURRIER 35-3	SI
285702	WELL	PR	01/01/2011	GW	077-09104	CURRIER 36-4	PR

General Comment:

[COGCC Inspection Report Summary](#)
 On Monday 11/16/20 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at LARAMIE ENERGY LLC Currier /26-15 Pad, Location #334528 in Mesa County Colorado.
 While there, I observed normal production operations.
 During this inspection the following possible compliance issues were observed: Sediment migrating off of location and on to access road due to tracking. See photo #2250, #2251, #2252, #2253 and #2254 with a corrective action date of 12/1/20.
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 10		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 10		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Separate containment			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	285683	Type:	WELL	API Number:	077-09095	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	285684	Type:	WELL	API Number:	077-09096	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	285685	Type:	WELL	API Number:	077-09097	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	285687	Type:	WELL	API Number:	077-09098	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	285688	Type:	WELL	API Number:	077-09099	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	285692	Type:	WELL	API Number:	077-09100	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	285694	Type:	WELL	API Number:	077-09101	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	285696	Type:	WELL	API Number:	077-09102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID: 285699 Type: WELL API Number: 077-09103 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced June 2020

Corrective Action: _____ Date: _____

Facility ID: 285702 Type: WELL API Number: 077-09104 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Ditches						
		Ditches				
Other	Fail					Tracking occurring from location to access road
Gravel						
Compaction	Fail					
		Gravel				
		Sediment Traps				
Berms						
Sediment Traps						
		Check Dams				

Comment: Sediment migrating off of location and on to access road due to tracking. See photo #2250, #2251, #2252, #2253 and #2254

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 12/01/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802107	Photos for Insp. #699802106	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292533