

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2020

Submitted Date:

11/11/2020

Document Number:

688800819

FIELD INSPECTION FORM

Loc ID 325624 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Heil, John		john.heil@state.co.us	
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215120	WELL	PR	07/30/1984	GW	067-06725	BEUTEN B 1	EI

General Comment:

On November 6, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Beuten B #1. For the most recent field inspection report of this facility, please refer to document #693902146.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance. Simcoe LLC listed as the operator of this location.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Posted on location sign.	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Lube Oil		<= 1 bbl	
Comment:	Stained gravel beneath Oil Lift equipment.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 12/11/2020

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		
Corrective Action:			Date:
Type: Gas Meter Run	#		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Linear rod pump and artificial lift equipment.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:	Telemetry equipment.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215120 Type: WELL API Number: 067-06725 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Ditches	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.
Culverts	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On November 6, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Beuten B #1. For the most recent field inspection report of this facility, please refer to document #693902146. During this inspection stained gravel was observed beneath the Oil Lift equipment, see attached photo.	hughesjo	11/11/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402530515	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5289194
688800820	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5289192