

KP Kauffman – Follow-up COGCC Inspection Photos
Location: UPPR 43 PAN AM G Consolidation #2 OLF Release
Spill ID # 478086 Date 11/06/2020



**KPK roustabout crew in process of completing HDPE poly fusion welding to construct new consolidation flowline;
View S from WCR 4**



View of existing (abandoned/ OOS) flowline marked with pin flags; view of new flowline trench/ spoil pile (realignment) to the west; View looking S-SE

KP Kauffman – Follow-up COGCC Inspection Photos
Location: UPPR 43 PAN AM G Consolidation #2 OLF Release
Spill ID # 478086 Date 11/06/2020



View of UPPR 43 PAN AM G Consolidation flowline trench after being backfilled and re-contoured; Looking N-NW



View into SE flowline isolation valve can; Valve handle

KP Kauffman – Follow-up COGCC Inspection Photos
Location: UPPR 43 PAN AM G Consolidation #2 OLF Release
Spill ID # 478086 Date 11/06/2020




View and location of NW isolation valve; looking SE




View and location of SE isolation valve; looking NW

KP Kauffman – Follow-up COGCC Inspection Photos
Location: UPPR 43 PAN AM G Consolidation #2 OLF Release
Spill ID # 478086 Date 11/06/2020



**Flowline pressure testing chart; Satisfactory test for new/
 repaired flowline segment and SE isolation valve**



**Flowline pressure testing chart; Satisfactory test for new/
 repaired flowline segment and NW isolation valve**