

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /150 Pad

Location ID: 334554



Photo #2291 from entrance to location.



Photo #2292 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /150 Pad

Location ID: 334554



Photo #2293 Rutting occurring due to lack of stabilization.



Photo #2294 Tracking occurring from location to access road.

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /150 Pad

Location ID: 334554



Photo #2295 Access road.