

Inspection Photos

API: 071-07412

Operator: TIMBER CREEK OPERATING
OGRIS OPERATING LLC

Inspection Date: 11/19/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 11/19/2020

Inspection Photos



Photo 1. There is vehicle rutting at the beginning of the access road from the main road in Bingham Canyon. This section of road is directing stormwater down the road to the main road. BMP's such as gravel and water bars are needed to prevent rutting and road degradation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 11/19/2020

Inspection Photos



Photo 2. Facing back down the access road shows vehicle rutting. This issue has previously been documented and needs to be repaired and prevented.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 11/19/2020

Inspection Photos



Photo 3. Storm water erosion is occurring down the side of the road. BMP's need to be installed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 11/19/2020

Inspection Photos



Photo 4. Facing toward the location. Storm water erosion is occurring down the side of the road. BMP's need to be installed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 11/19/2020