



Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		Date: _____
Corrective Action:	<input style="width: 100%;" type="text"/>		
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained Soil at Wellhead, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e." Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>12/02/2020</u>
Type	STORAGE OF SUPL		
Comment:	Unmarked Riser at Wellhead, see photos		
Corrective Action:	Comply with Rule 603.f.		Date: <u>11/20/2020</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead Parts at Pumping Unit. See photos		
Corrective Action:	Comply with Rule 603.f.		Date: <u>12/02/2020</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Barbed Wire		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		

Comment:	TA Wellhead - Blue TA Tag installed		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 245843 Type: WELL API Number: 123-13638 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Unused Wellhead parts at Pumping Unit, Unmarked Riser at Wellhead, Stained Soil at Wellhead</a>	petrie	11/16/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402534212	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292538">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292538</a>
696302666	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292528">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292528</a>