

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PU, Horses head have been lying on the ground and not attached to WH For over 1 yr and possibly since 11/2016 as documented in Inspection Doc #s 681901686, 693500943 and 699300500		
Corrective Action:	Comply with Rule 603.f	Date:	08/31/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Ancillary equipment		1	electric panel meter box and transformer	
Corrective Action:				Date:
Bradenhead		1	appears to be plumbed to surface	
Corrective Action:				Date:
Pump Jack		1	horses head lying on ground since 11/2016 and no electric motor.	
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240786 Type: WELL API Number: 123-08574 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA since 8/2015

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: last test is past 1 year and needs to be done annually.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 11/18/2020 at approximately 1250 hrs. I, Inspector Robbie Revas, conducted an on-site inspection at a KP Kauffman site, Jillson #3, API# 05-123-08356 in Weld County Colorado. While there, I observed a well site.TA since 8/2015 Form 4 TA Status was submitted to the COGCC 8-6-15 Doc#400880968. During this inspection the following possible compliance issues were observed: 603.f unused equipment:PU, Horses head has been lying on the ground and not attached to WH For over 1 yr and possibly since 11/2016 as documented in Inspection Doc #s 681901686, 693500943 and 699300500. Rule 206: Bradenhead test reporting. See attached location photos. Weather: clear, Location: dry. Sending report to DNR COGCC Enforcement due to non compliance. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	11/18/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402535900	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293860
699302986	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293851