

Location			
Lease Road:			
Type	Access		
comment:	well is located between several houses		
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	dead weead inside fencing need to be addressed		
Corrective Action:	Comply with rule 603.f		Date: <u>12/18/2020</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	chain link topped with barb wire		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	electric motor		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panels, meter box and transformer		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240965 Type: WELL API Number: 123-08753 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error
 Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
 End Surf Csg Pressure: _____
 Comment: test is over 1 year old and needs to be done annually
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 11/18/2020 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Charles Elzi Estate at API #05-123-08753 in Weld County Colorado. While there, I observed a wellsite, PR at time of inspection During this inspection the following possible compliance issues were observed: 603.f housekeeping: dead weed inside of fencing around PU. CA date 12-18-2020. 206 reporting: Braden head test is over 1 year. See attached photos. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	11/18/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402535901	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293861
699302988	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293852