

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2020

Submitted Date:

11/18/2020

Document Number:

701100770

**FIELD INSPECTION FORM**
 Loc ID 430567 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430566	WELL	PR	12/02/2013	GW	045-21747	Strait SG 341-22	PR
430568	WELL	PR	12/02/2013	GW	045-21748	Strait SG 431-22	PR
430569	WELL	PR	11/11/2013	GW	045-21749	Strait SG 331-22	PR
430570	WELL	PR	12/02/2013	GW	045-21750	Strait SG 41-22	PR
430571	WELL	PR	11/07/2013	GW	045-21751	Strait SG 42-22	PR
430572	WELL	PR	11/07/2013	GW	045-21752	Strait SG 342-22	PR
430573	WELL	PR	12/02/2013	GW	045-21753	Strait SG 31-22	PR
430574	WELL	PR	11/10/2013	GW	045-21754	Strait SG 441-22	PR
430575	WELL	PR	11/07/2013	GW	045-21755	Strait SG 442-22	PR
430576	WELL	PR	12/02/2013	GW	045-21756	Strait SG 532-22	PR
430577	WELL	PR	11/07/2013	GW	045-21757	Strait SG 432-22	PR
430578	WELL	PR	11/07/2013	GW	045-21758	Strait SG 332-22	PR

**General Comment:****COGCC Follow Inspection Report Summary**

1, Inspector Mike Longworth, conducted a follow up to 09/22/2020 inspection doc # 701100414 at TEP ROCKY MOUNTAIN LLC, SG 42 22, Location ID: 430567 in Garfield County, Colorado.

2 unmarked deadmen south west end of wells.

Install proper guy line markers per Rule 1003.a

CA Date: 12/04/2020

Crew on location building a retaining wall along cut slope by separator and pipe line previously covered by sediment slide. No observed repair to cut slope behind tank battery.

Install or repair required BMPs per Rule 1002.f.(2)C

CA Date 10/09/2020

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 2		corrective date
Comment:	2 unmarked deadmen south west end of wells.		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 12/04/2020

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	430566	Type:	WELL	API Number:	045-21747	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	430568	Type:	WELL	API Number:	045-21748	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	430569	Type:	WELL	API Number:	045-21749	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	430570	Type:	WELL	API Number:	045-21750	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	430571	Type:	WELL	API Number:	045-21751	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	430572	Type:	WELL	API Number:	045-21752	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	430573	Type:	WELL	API Number:	045-21753	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	430574	Type:	WELL	API Number:	045-21754	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	430575	Type:	WELL	API Number:	045-21755	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	430576	Type:	WELL	API Number:	045-21756	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	430577	Type:	WELL	API Number:	045-21757	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	430578	Type:	WELL	API Number:	045-21758	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail			Vehicle Tracking	Fail	Soft pad base rutting causing tracking.

Comment: Crew on location building a retaining wall along cut slope by separator and pipe line previously covered by sediment slide. No observed repair to cut slope behind tank battery.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 10/09/2020

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402534985	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293158">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293158</a>
701100772	Inspection 701100770 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293156</a>