

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWNE
Location ID: 335274**



**Ruts on road in front of separators and
tank battery.**

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWE
Location ID: 335274



Mining of rocks from behind wells.



Sediment built up around wells.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWE
Location ID: 335274**



Storm water and sediment flowing to well heads.



Unused pipe.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWNE
Location ID: 335274**



Diversion ditch is blocked off by rock mining.



Storm water and sediment flowing to well heads.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWNE
Location ID: 335274**



Unused pipe.



**Storm water washing over location and
riling reclaim area.**

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWNE
Location ID: 335274



Ditch needs maintained.



**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWN
Location ID: 335274**



Dead debris on edge of location.

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWNE
Location ID: 335274



Rutting on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWNE
Location ID: 335274



Rutting on access road.



Road ditches need maintained.

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWNE
Location ID: 335274



Road ditches need maintained.



Road ditches need maintained.

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWNE
Location ID: 335274



Dead debris along side of access road.



**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 32NWE
Location ID: 335274**



Check dam needs maintained.



Check dam needs maintained.