

Inspection Photos
Location Name: Ignacio 33-7 #19A
API: 05-067-08071



Open topped steel produced water vessel. Ensure that secondary containment berm has adequate capacity.



Secondary containment berm does not appear to have adequate capacity per Rule 605.a.4.

Inspection Photos
Location Name: Ignacio 33-7 #19A
API: 05-067-08071



Ignacio 33-7 #19A well head and chemical injection system.



Chemical injection system on secondary containment.