

Inspection Photos
Location Name: Ignacio 33-7 #19
API: 05-067-05743



Ignacio 33-7 #19 location photo.



Ignacio 33-7 #19 separator and fiberglass open topped tank.

Inspection Photos
Location Name: Ignacio 33-7 #19
API: 05-067-05743



NFPA placard is peeling off of tank.



Secondary containment berm does not appear to have adequate capacity per Rule 605.a.4.