

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2020

Submitted Date:

11/25/2020

Document Number:

695103622**FIELD INSPECTION FORM**Loc ID 333484 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89154	WELL	PR	05/05/2003	GW	071-06733	SIERRA 43-29 TR	PR
217693	WELL	TA	10/20/2014	GW	071-06472	SIERRA 43-29	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Phone 2: WELL SIGN FOR ORIGINAL WELL IS NOT POSTED.		
Corrective Action:	POST SIGN FOR ORIGINAL WELL, COMPLY WITH RULE 210.b.	Date:	12/25/2020

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Phone 4: UNUSED EQUIPMENT ON ORIGINAL WELL (ENGINE SKID IS UNUSED ON TA WELL).		
Corrective Action:	REMOVE ENGINE SKID, COMPLY WITH RULE 603.f.	Date:	02/25/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Phone 3: BRADENHEAD ON ORIGINAL WELL IS NOT PLUMBED TO SURFACE.		
Corrective Action:	PROVIDE ACCESS TO BRADENHEAD, COMPLY WITH NEW RULE 341.	Date:	12/25/2020
Type: Bradenhead	# 2		
Comment:	BRADENHEAD FOR TR WELL IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			

Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 89154 Type: WELL API Number: 071-06733 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: Facility ID: 217693 Type: WELL API Number: 071-06472 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In☒ Temporarily AbandonedReminder: Comment: LAST MIT 9-2019Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402540949	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298806">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298806</a>
695103623	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298786">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298786</a>