

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER
Comment:	Phone 3: AREA OF IMPACTED SOIL NEAR PROME MOVER (DRIVEHEAD ENGIN SKID). Phone 4: AREA OF IMPACTED SOIL AROUND WELLHEAD AND ALONG HYDO HOSE PATH.
Corrective Action:	Conduct maintenance on equipment, Remove stained material and review self inspection processes. Comply with rule 1002.F.(2)F

Date: 12/25/2020

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Gas Meter Run	# 1
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead	# 1
Comment:	IS PLUMBED TO SURFACE

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 89196 Type: WELL API Number: 071-06775 Status: PR Insp. Status: PR

Producing Well

Comment: WELL IS REPORTED AS PRODUCING, HOWEVER AT TIME OF INSPECTION THE VALVES ON THE WELL ARE SET TO PRODUCE BUT THE PRODUCTION RECORD SHOWS 0 MCF PRODUCED IN THE LAST 2 DAYS.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Phone 5: OILY WASTE IN PRIME MOVER ENGINE SKID.

Corrective Action: Comply with general provisions of the oil and gas act for wildlife protection.

Date: 11/27/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402540951	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298807
695103639	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298793