

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/24/2020

Submitted Date:

11/24/2020

Document Number:

701100810**FIELD INSPECTION FORM**Loc ID 335274 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211531	WELL	PR	10/28/1998	GW	045-07291	UNOCAL GM 31-32	PR
271024	WELL	PR	06/15/2004	GW	045-09828	WILLIAMS GM 531-32	PR
271025	WELL	PR	06/06/2004	GW	045-09829	WILLIAMS GM 431-32	PR
271026	WELL	PR	06/09/2004	GW	045-09830	WILLIAMS GM 210-32	PR

General Comment:**COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W 32NWNE, Location ID: 335274 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Access road and storm water bmps need maintained.

Location and access roadside ditches have dead debris.

Trash around location. Cans, bottles, food packages, paper plate, etc. Piece of unused pipe near wells and another piece of unused pipe by yellow deadman marker.

Diversion ditch is blocked off by rock mining. Storm water and sediment flowing from blocked ditch to well heads then washing over location and riling reclaim area. Ditch along location needs maintained. Road ditches and check dams need maintained. Ruts on roads are creating riling.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:	Access road and storm water bmps need maintained.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash around location. Cans, bottles, food packages, paper plate, etc. Piece of unused pipe near wells and another piece of unused pipe by yellow deadman marker.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/04/2020
Type	DEBRIS		
Comment:	Location and access roadside ditches have dead debris.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/04/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Braden head accessible for monitoring.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	211531	Type:	WELL	API Number:	045-07291	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	271024	Type:	WELL	API Number:	045-09828	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	271025	Type:	WELL	API Number:	045-09829	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	271026	Type:	WELL	API Number:	045-09830	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Vehicle Tracking	Fail	
Ditches	Fail					
		Ditches	Fail			
		Check Dams	Fail			

Comment: Diversion ditch is blocked off by rock mining. Storm water and sediment flowing from blocked ditch to well heads then washing over location and riling reclaim area. Ditch along location needs maintained. Road ditches and check dams need maintained. Ruts on roads are creating riling.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/11/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402540193	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298118
701100811	Inspection 701100810 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298117