

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2020

Submitted Date:

12/02/2020

Document Number:

700701965**FIELD INSPECTION FORM**

Loc ID 335540	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>950 17TH STREET, SUITE 1900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>19</u> Number of Comments <u>3</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested <b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289262	WELL	PR	07/01/2020	GW	045-13707	BURCKLE A1	PR
289263	WELL	PR	07/07/2011	GW	045-13706	Burckle Federal A2	PR
289264	WELL	PR	07/01/2020	GW	045-13705	BURCKLE A3	PR
289265	WELL	XX	03/12/2018	LO	045-13704	Burckle A4	XX
289997	WELL	PR	07/01/2020	GW	045-13960	BURCKLE A7	PR
289998	WELL	DG	12/13/2012	GW	045-13959	Burckle A8	DG
291710	WELL	PR	07/01/2020	GW	045-14516	BURCKLE A11	PR
291712	WELL	PR	07/01/2020	GW	045-14515	BURCKLE A9	PR
297862	WELL	DG	10/07/2019	LO	045-16989	Burckle A5	DG
297863	WELL	DG	12/20/2012	GW	045-16990	Burckle A6	DG
298250	WELL	PR	07/02/2011	GW	045-17096	BURCKLE FED CA A10	PR
298251	WELL	PR	08/15/2011	GW	045-17097	BURCKLE FED CA A12	PR
422091	WELL	PR	07/08/2011	GW	045-20490	Burckle Federal A14	PR
422095	WELL	PR	08/15/2011	GW	045-20491	Burckle Federal A13	PR

<b>General Comment:</b>           
---

COGCC Inspection Report Summary

On Wednesday 12/2/20 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at URSA Burckle A, at Location # 335540 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking
- No evidence of tracking control BMP's
- Erosion and sediment migration behind tank batteries and in south east corner at drain/sediment trap needs maintained
- One (1) Dead man is unmarked
- Debris next to separators

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	911
Corrective Action:	
Date:	_____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	debris next to separators		
Corrective Action:	remove debris	Date:	01/06/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 9		
Comment:	All meters have been calibrated on location within the past year.		

Corrective Action:		Date:	
Type: Bradenhead	# 9		
Comment:	two (2) braden heads are tied into sales and all Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:	one (1) deadman is unmarked		
Corrective Action:	mark or remove deadman		Date: 01/06/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:	one (1) tank is heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLs	STEEL AST		,
Comment:	one (1) tank is heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type	Ignitor/Combustor				
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	289262	Type:	WELL	API Number:	045-13707	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	289263	Type:	WELL	API Number:	045-13706	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	289264	Type:	WELL	API Number:	045-13705	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	289265	Type:	WELL	API Number:	045-13704	Status:	XX	Insp. Status:	XX
Facility ID:	289997	Type:	WELL	API Number:	045-13960	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	289998	Type:	WELL	API Number:	045-13959	Status:	DG	Insp. Status:	DG
Facility ID:	291710	Type:	WELL	API Number:	045-14516	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291712	Type:	WELL	API Number:	045-14515	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297862	Type:	WELL	API Number:	045-16989	Status:	DG	Insp. Status:	DG
Facility ID:	297863	Type:	WELL	API Number:	045-16990	Status:	DG	Insp. Status:	DG
Facility ID:	298250	Type:	WELL	API Number:	045-17096	Status:	PR	Insp. Status:	PR

<b><u>Producing Well</u></b>			
Comment:	producing		
Corrective Action:		Date:	
Facility ID: 298251    Type: WELL    API Number: 045-17097    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	producing		
Corrective Action:		Date:	
Facility ID: 422091    Type: WELL    API Number: 045-20490    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	producing		
Corrective Action:		Date:	
Facility ID: 422095    Type: WELL    API Number: 045-20491    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	producing		
Corrective Action:		Date:	

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains						
Berms		Culverts				
Ditches		Ditches				
Sediment Traps						

Comment: • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)  
 BMP's require maintenance which in turn can lead to tracking  
 • No evidence of tracking control BMP's  
 • Erosion and sediment migration behind tank batteries and in south east corner at drain/sediment trap needs maintained

Corrective Action: **Maintain BMP's**  
**Provide proof of tracking control BMP's**

Date: 01/06/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701970	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301887">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301887</a>