

Inspection Photos

Operator: Hilcorp Energy
API: 067-06464
Date: 12/1/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southern edge of the working area, facing westward.



Photo 3. View of Scotch thistles in a post-flowering condition, in the southern project area. Approximately 200 individuals observed.



Photo 4. View of the western project area from the southwestern corner facing northward. Gravel and cobble placed where water flows off of the well pad. This will need to be monitored and maintained when erosion occurs here.



Photo 4. View of unreclaimed well pad from the southern edge facing southeastward.