

Inspection Photos

Operator: Hilcorp Energy
API: 067-09948
Date: 11/20/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the project area from the well pad entrance facing center. Vegetation on the well pad is largely weeds such as kochia, Russian thistle, and yellow sweetclover.



Photo 3. View of the northern project area from the northeastern corner facing westward. Cut slope is largely bare and rapidly eroding.



Photo 4. View of unknown soil material that appears to be cuttings, placed at the base of the cut-slope.



Photo 5. View of dense Russian knapweeds in a dormant vegetative condition, within the northwestern portion of the well pad. 1000s of individuals observed.



Photo 6. View of southern project area sparsely vegetated with alfalfa.



Photo 7. View of wired gate near entrance to project area.



Photo 8. View of access road facing westward. Little use of road observed.



Photo 9/10. View of closed gates after leaving location.