

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**API: 067-09084**  
**Date: 11/20/2020**



Photo 1. View of the project area from the well pad entrance facing center. Reclamation is not conducted.



Photo 2. View of eroding cut-slope within the southern project area. Erosional channels, exposed roots, and sediment plumes observed.



Photo 3. Another view of eroding cut-slope within the southern project area.



Photo 4. View of unreclaimed well pad from the southern edge facing southeastward.