

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2020

Submitted Date:

12/03/2020

Document Number:

696202065

FIELD INSPECTION FORMLoc ID 314281 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10027

Name of Operator: C & J FIELD SERVICES

Address: 3650 COUNTY RD #2

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
		candjfield@centurytel.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228179	WELL	PA	08/17/2012	OW	103-01123	SMITH-HARRIS 2-2	PA
314281	LOCATION	CL			-	SMITH-HARRIS-61N102W 10NENW	RI

General Comment:

On 12/1/2020, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at C&J Field Service's Smith-Harris #2-2 location in Rio Blanco County, Colorado.

This inspection is a follow up to inspection #692400855 and #696201120 to document compliance for the following corrective actions:

1004: Comply with 1004 rules and conduct reclamation, remove surface equipment.

On 7/9/2020, Operator contacted Reclamation specialist regarding the corrective actions. Operator stated above ground flowline and electrical equipment remaining on the Location is still in use. Operator was directed to submit a Form 4 sundry identifying the equipment's current use on the location, and wells equipment is associated with. To date no documentation has been submitted by Operator.

It was observed in this inspection that flowline and electrical equipment remains on Location. It was also observed that the flowline equipment identified by the Operator does not appear to have been registered/mapped pursuant to the 1100 Rules. Additionally, flowline integrity concerns still exist as leaks and corrosion remain evident.

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 228179 Type: WELL API Number: 103-01123 Status: PA Insp. Status: PA

Flowline

#1	Type:	1 of Lines
----	-------	------------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

☒ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Previous and current inspections observed flowline riser and pipe equipment remaining on the Location with integrity concerns (leaks/corrosion). Previous inspections required Operator to comply with 1004 rules and remove. Corrective actions have not been addressed; Integrity concerns also not addressed.

Corrective Action: There are three corrective actions being provided:

- 1) Immediately maintain active and inactive flowlines and crude oil transfer lines to meet 1102 Rules.
- 2) Immediately contact COGCC Western Integrity Inspector R. Murray (g.richard.murray@state.co.us) and provide annual pressure testing data per Rule 1104.f. (1)A attached to a Form 4 Sundry.
- 3) Immediately submit an eForm 44 Flowline Report for flowline registration pursuant to 1101 Rules: An off-location flowline in existence prior to May 1, 2018, required registration by October 31, 2019.

Note to Operator: Ensure all off-location flowlines meet the 1100 Series Rules.

Date: 10/31/2019

Facility ID: 314281 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed **Fail** _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

It was observed in this inspection that flowline and electrical equipment remain on the Location. See "related facilities" for additional information regarding flowline. Corrective action requiring reclamation and removal of electrical equipment has not been addressed.

Entire access road has not been reclaimed per the corrective actions. See Photo 6. No evidence of desirable perennial vegetative germination, reseeding is required.

Inspection #692400855 required reclamation activities to be completed by end of Fall 2019; The CA date of 12/20/2019 remains applicable.

Corrective Action:

Comply with Rule 1004.a: Perform Final Reclamation per COGCC 1004 Rules including removal of equipment/risers, stained soil, de-compaction & re-seeding of site, and reclamation of access road. Install appropriate BMPs to stabilize location until vegetation establishes.

Date **12/20/2019**

Overall Final Reclamation

FailWell Release on Active Location ☐Multi-Well Location ☐**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202066	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302783