

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2020

Submitted Date:

12/03/2020

Document Number:

700701978

FIELD INSPECTION FORM

 Loc ID 335550 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10447
 Name of Operator: URSA OPERATING COMPANY LLC
 Address: 950 17TH STREET, SUITE 1900
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293098	WELL	PR	12/14/2012	GW	045-14882	DIXON A8	PR
293099	WELL	DG	05/18/2012	GW	045-14883	DIXON A7	DG
293100	WELL	PR	10/15/2012	GW	045-14884	DIXON A3	PR
293101	WELL	PR	09/13/2012	GW	045-14885	DIXON A2	PR
293102	WELL	PR	12/14/2012	GW	045-14886	DIXON A1	PR
293103	WELL	XX	03/26/2018	LO	045-14887	Dixon A4	XX
293104	WELL	PR	12/14/2012	GW	045-14888	DIXON A5	PR
293105	WELL	PR	12/14/2012	GW	045-14889	DIXON A6	PR
293106	WELL	PR	09/12/2012	GW	045-14890	DIXON A9	PR
293152	WELL	XX	03/12/2018	LO	045-14901	DIXON A15	XX
293154	WELL	XX	03/12/2018	LO	045-14903	DIXON A12	XX
293156	WELL	XX	03/12/2018	LO	045-14904	DIXON A13	XX
293157	WELL	PR	12/14/2012	GW	045-14905	DIXON A11	PR
293158	WELL	XX	03/12/2018	LO	045-14906	DIXON A10	XX

General Comment:

COGCC Inspection Report Summary

On Wednesday 12/3/20 at approximately 1430, I, Inspector Scott Ramsey, conducted a routine inspection at URSA Dixon A, at Location # 335550 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking
- No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			

Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	STEEL AST		
Comment:	shared containment with condensate tanks				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		
Comment:	one (1) tank is heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:		
Type	Ignitor/Combustor	
Comment:		
Corrective Action:	Date:	

Inspected Facilities									
Facility ID:	293098	Type:	WELL	API Number:	045-14882	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293099	Type:	WELL	API Number:	045-14883	Status:	DG	Insp. Status:	DG
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293100	Type:	WELL	API Number:	045-14884	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293101	Type:	WELL	API Number:	045-14885	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293102	Type:	WELL	API Number:	045-14886	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293103	Type:	WELL	API Number:	045-14887	Status:	XX	Insp. Status:	XX
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293104	Type:	WELL	API Number:	045-14888	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293105	Type:	WELL	API Number:	045-14889	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293106	Type:	WELL	API Number:	045-14890	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 293152 Type: WELL API Number: 045-14901 Status: XX Insp. Status: XX

Facility ID: 293154 Type: WELL API Number: 045-14903 Status: XX Insp. Status: XX

Facility ID: 293156 Type: WELL API Number: 045-14904 Status: XX Insp. Status: XX

Facility ID: 293157 Type: WELL API Number: 045-14905 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 293158 Type: WELL API Number: 045-14906 Status: XX Insp. Status: XX

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
		Ditches				

Comment:
 • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance which in turn can lead to tracking
 • No evidence of tracking control BMP's

Corrective Action:
 Maintain all BMP'S
 Provide proof of tracking control BMP's

Date: 01/07/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701984	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302803