

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/04/2020

Submitted Date:

12/04/2020

Document Number:

696302722

FIELD INSPECTION FORM
 Loc ID 428441 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10503

Name of Operator: RED HAWK PETROLEUM LLC

Address: 575 N DAIRY ASHFORD STE 201

City: HOUSTON State: TX Zip: 77079

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Boyd, William		wboyd@pedevco.com	All Inspections
Shepard, DeAnn		dshepard@pedevco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428440	WELL	PR	07/06/2012	OW	123-35357	Ford Family Trust 2H	PR

General Comment:

This is a Follow-Up Inspection to FIR 696300715

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Battery Sign at Entrance does not reflect Operator, see photos		
Corrective Action:	Comply with Rule 210.b.	Date:	01/04/2021
Type	WELLHEAD		
Comment:	Wellhead Sign does not reflect Operator, see photos		
Corrective Action:	Comply with Rule 210.b.	Date:	01/04/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Rods at Pumping Unit, see photos		
Corrective Action:	Battery Sign at Entrance does not reflect Operator, see photos	Date:	01/04/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused latrine at West side of Location, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	01/04/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused Supply Pot west of Heater Treater, see photos		
Corrective Action:	Battery Sign at Entrance does not reflect Operator, see photos	Date:	01/04/2021
Type	OTHER		
Comment:	Stained Soil at Wellhead and Flare. See photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."	Date:	01/04/2021
Type	DEBRIS		
Comment:	Unused Belts at Pumping Unit and NE Corner of location. See photos		
Corrective Action:	Comply with Rule 603.f.	Date:	01/04/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Vertical Heater Treater	# 1			
Comment:				
Corrective Action:				Date:
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Flare	# 1			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		Shares berm with the Crudel Oil Tanks					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	3	400 BBLs	STEEL AST		40.524730,-104.030630		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type	Field Flare						
Comment:							
Corrective Action:						Date:	

Inspected Facilities									
Facility ID:	428440	Type:	WELL	API Number:	123-35357	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	431160	400275215	
	431160	400275215	

COGCC Comments

Comment	User	Date
Routine Follow-Up Field Inspection. Day Tank Containment and Chemical at Pumping Unit now have Wildlife netting. New Corrective Actions - Stained Soil at Wellhead and Flare. Unused Rods still remain at Pumping Unit. Unused Belts at Pumping Unit and NE corner. Unused Supply Pot still remain. Wellhead Sign and Battery Sign at Entrance Still do NOT reflect current Operator.	petrie	12/04/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302723	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5303685