

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2020

Submitted Date:

12/07/2020

Document Number:

696302730**FIELD INSPECTION FORM**Loc ID 327473 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 53790Name of Operator: MARKUS PRODUCTION, INCAddress: 39 FAIRWAY LANECity: LITTLETON State: CO Zip: 80123**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Mark	(720) 350-8858	mark@markusproduction.com	
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246945	WELL	SI	04/01/2020	GW	123-14742	LIVENGOD 7-7	TA

**General Comment:**[Follow-Up Inspection to FIR 636301278 dated 02.12.2020](#)

## Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	All Production Equipment remain - Well appears to have been Plugged and Abandoned on 08.28.2020. (90 Days from plugging) Heater Treater, Vertical Separator, Crude Oil Tanks, and Pit.		
Corrective Action:	Comply with Rule 1004.a	Date:	03/08/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			

Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.591240,-104.023420
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 246945 Type: WELL API Number: 123-14742 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well appears to be have been Plugged and Abandoned on 08.28.2020 per Form 42 PA 402475054 dated 08.26.2020.  
Form 6 Approved 402450318 dated 07.31.2020  
No Form 6 Subsequent appears to be on File or in Review file. Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, will be filed with the Director. The abandonment details will include an account of the manner in which the abandonment or plugging work was performed.

Corrective Action: File Form 6 Subsequent with Engineering Department per Rule 311.b.

Date: 01/08/2021

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Seeding				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water

Lined:

Pit ID:

Lat: 40.591570Long: -104.023250Reference Point: SE

Other: \_\_\_\_\_

Length: 10Width: 10**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**Netting Type: Metal GridNetting Condition: GoodComment: Holes have been repaired.

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 12/02/2020 at approximately 11:34, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Markus Production INC, Livengood 7-7, Location ID #327473 in Weld County, Colorado.</p> <p>While there, I observed Production Operations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>All Production Equipment remain - Well appears to have been Plugged and Abandoned on 08.28.2020. Flowline from Wellhead to Heater, Heater Treater, Vertical Separator, Crude Oil Tanks, and Pit. Comply with Rule 1004.a (90 Days from plugging)</p> <p>Well appears to be have been Plugged and Abandoned on 08.28.2020 per Form 42 PA 402475054 dated 08.26.2020.</p> <p>Form 6 Approved 402450318 dated 07.31.2020</p> <p>No Form 6 Subsequent appears to be on File or in Review file. Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, will be filed with the Director. The abandonment details will include an account of the manner in which the abandonment or plugging work was performed. File Form 6 Subsequent with Engineering Department per Rule 311.b.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	12/07/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302731	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5304645">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5304645</a>