

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2020

Submitted Date:

12/01/2020

Document Number:

688800837

FIELD INSPECTION FORM

Loc ID 333406 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 74650
Name of Operator: RIM OPERATING INC
Address: 5 INVERNESS DRIVE EAST
City: ENGLEWOOD State: CO Zip: 80112

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Ortiz, Liz	303-799-9828 Ext 304	lortiz@rimop.com	All Inspections
Rector, Mike	720-220-1677	mhr@rimop.com	All Inspections
Elledge, Randy	505-320-4969	relledge@rimop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216465	WELL	PR	04/22/1997	GW	067-08071	IGNACIO 33-7 19A	EI

General Comment:

On November 19, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Rim Operating Inc. Ignacio 33-7 #19A. For the most recent field inspection report of this facility, please refer to document #693902514.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near separator.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Signs on tank list capacity, contents, and NFPA placard.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Post and wire fencing around separator and produced water vessel.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	SE anchor was not observed during this inspection.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		37.070532,-107.654008

Comment: [Expanded metal cover.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Secondary containment berm does not appear to have adequate capacity.](#)

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).	Date:	<u>02/01/2021</u>
--------------------	--	-------	-------------------

Wells Served By Facilities Above

AirsID

API Number
067-08071

API Number	AirsID
------------	--------

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 216465 Type: WELL API Number: 067-08071 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical container.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On November 19, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Rim Operating Inc. Ignacio 33-7 #19A. For the most recent field inspection report of this facility, please refer to document #693902514. Secondary containment berm does not appear to have adequate capacity.	hughesjo	12/01/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402543971	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301040
688800838	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301039