

Inspection Photos
Location Name: Cascade Creek 697-09-61
Location ID: #335889
Inspection Date: December 4, 2020



Photo #1 – Sign located at entrance to pad.



Photo #2 – View of wellheads and tank battery from south.



Inspection Photos
Location Name: Cascade Creek 697-09-61
Location ID: #335889
Inspection Date: December 4, 2020



Photo #3 – View of tank battery from south.



Photo #4 – Damaged NFPA placard on steel AST.



Inspection Photos

Location Name: Cascade Creek 697-09-61

Location ID: #335889

Inspection Date: December 4, 2020



Photo #5 – Accumulation of ice inside of secondary containment area.



Photo #6 – Unmarked flowline riser located northeast of tank battery.



Inspection Photos

Location Name: Cascade Creek 697-09-61

Location ID: #335889

Inspection Date: December 4, 2020



Photo #7 – Overview of unnamed creek located east of Cascade Creek 697-09-61 Pad, looking south.

Photo #8 – Creek contained ice on inspection date.



Inspection Photos

Location Name: Cascade Creek 697-09-61

Location ID: #335889

Inspection Date: December 4, 2020



Photo #9 - Overview of unnamed creek located west of Cascade Creek 697-09-61 Pad, looking north.



Photo #10 - Creek contained ice on inspection date.

