

Inspection Photos

Operator: BP America
API: 067-08935
Date: 12/7/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope, facing southward. Revegetation is progressing with crested wheatgrass, western wheatgrass, intermediate wheatgrass, and sand dropseed.



Photo 3. View of the southern project area facing eastward.




Photo 4. View of musk thistles along the access road. Approximately 200 individuals observed.



Photo 6. View of the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of squirreltail, blue grama, and penstemon spp.



Photo 7. View of closed gate after leaving location.