

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

12/02/2020

Document Number:

688800843**FIELD INSPECTION FORM**Loc ID 333217 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10734Name of Operator: HIGH RIVER RESOURCES OPERATING LLCAddress: 3838 OAK LAWN AVE SUITE 710City: DALLAS State: TX Zip: 75219**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Imel, Andrew		aimel@highriverllc.com	
Archuleta, Amy		aarchuleta@highriverllc.com	
Heil, John		john.heil@state.co.us	
Vaughn, Robert		rvaughn@highriverllc.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291219	WELL	PR	01/07/2009	GW	067-09377	KNIGHT GAS UNIT A-17	EI

General Comment:

On November 19, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the High River Resources Knight Gas Unit #A-17. For the most recent field inspection report of this facility, please refer to document #693901761.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near well head. API number reads "05-067-9377-00". Correct API # for well is 067-09377.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical container labels are faded and illegible.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	02/02/2021
Type	TANK LABELS/PLACARDS		
Comment:	Produced water vessel is labeled with contents, capacity, and has NFPA placard.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on location signs.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		

Comment: Trailer mounted.			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	Open Top		37.013496,-107.628472	
Comment: Expanded metal cover.						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
067-09377

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291219	Type:	WELL	API Number:	067-09377	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical container.
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 19, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the High River Resources Knight Gas Unit #A-17. For the most recent field inspection report of this facility, please refer to document #693901761.	hughesjo	12/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402544745	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301537
688800844	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301536