

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2020

Submitted Date:

12/02/2020

Document Number:

700600225**FIELD INSPECTION FORM**Loc ID 321871 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 34105Name of Operator: GILBERT-STEWART OPERATING LLCAddress: 1801 BROADWAY STE 200City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
GILBERT, KENT	303-534-1686	kgoil@msn.com	
,	,	dnr_cogccengineering@state.co.us	COGCC Engineering
,	,	dnr_cogccenforcement@state.co.us	COGCC Enforcement
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208289	WELL	TA	01/01/2020	OW	017-07224	AKERS 2	EI

General Comment:

Noise from gas venting observed during inspection. RKL gas monitor detected methane gas venting. No Form 4 to approve venting/flaring found on file for well. Contacted operator at listed emergency number (303) 534-1686 at the time of inspection and again on 12/2/2020 but no there was no answer. Voicemails left instructing operator to contact COGCC EPS was not returned at the time this inspection was issued.

Update 12/7/2020. Operator has complied with corrective actions. Venting has ceased after repair to leaking equipment that caused venting that was observed on 12/1/2020. Operator is installing new contact phone number week of 12/7/2020.

This is an environmental inspection only.

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Emergency contact number on lease sign is not monitored 24/7. No responses to voicemails left at the time of inspection were returned.Corrective Action: Install sign with emergency contact number that is monitored 24/7.

Date: 01/02/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 208289 Type: WELL API Number: 017-07224 Status: TA Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402544416	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301294
700600226	Gas monitor video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301291
700600227	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301292