

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2020

Submitted Date:

12/02/2020

Document Number:

700701966**FIELD INSPECTION FORM**

Loc ID 335539	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>950 17TH STREET, SUITE 1900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>16</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291673	WELL	PR	07/01/2020	GW	045-14477	MCPHERSON A3	PR
291678	WELL	XX	04/02/2018	LO	045-14474	McPherson A1	XX
291679	WELL	PR	05/22/2012	GW	045-14475	McPherson A8	PR
291680	WELL	PR	07/01/2020	GW	045-14476	MCPHERSON A4	PR
298100	WELL	PR	05/17/2012	GW	045-17067	McPherson A6	PR
298101	WELL	PR	07/01/2020	GW	045-17068	MCPHERSON A9	PR
298102	WELL	PR	06/11/2013	GW	045-17069	MCPHERSON A2	PR
298103	WELL	PR	05/23/2012	GW	045-17070	McPherson A12	PR
298104	WELL	PR	05/25/2012	OW	045-17071	McPherson A11	PR
298105	WELL	PR	05/22/2012	GW	045-17072	McPherson A7	PR

General Comment:

COGCC Inspection Report Summary

On Wednesday 12/2/20 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at URSA Mcpherson A, at Location # 335539 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking
- No evidence of tracking control BMP's
- Erosion and sediment migration (run off) on north side of location riling is occurring before and after sediment trap
- Sediment trap needs maintained

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	911
Corrective Action:	
Date:	_____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 9		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 9		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:	shared containment with condensate tanks					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:	one (1) tank is heated					
Corrective Action:						
Date:						

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291673	Type:	WELL	API Number:	045-14477	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291678	Type:	WELL	API Number:	045-14474	Status:	XX	Insp. Status:	XX
Facility ID:	291679	Type:	WELL	API Number:	045-14475	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291680	Type:	WELL	API Number:	045-14476	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298100	Type:	WELL	API Number:	045-17067	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298101	Type:	WELL	API Number:	045-17068	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298102	Type:	WELL	API Number:	045-17069	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298103	Type:	WELL	API Number:	045-17070	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298104	Type:	WELL	API Number:	045-17071	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	producing		
Corrective Action:		Date:	
Facility ID:	298105	Type:	WELL
API Number:	045-17072	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
Sediment Traps						
Ditches		Culverts				

Comment:
 • Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking
 • No evidence of tracking control BMP's
 • Erosion and sediment migration (run off) on north side of location riling is occurring before and after sediment trap
 • Sediment trap needs maintained

Corrective Action: **Maintain ALL BMP'S**
Provide proof of tracking control BMP's

Date: 01/06/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402545176	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301893
700701971	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301888