

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #2403 from entrance to location.



Photo #1976 from #699801876 inspection conducted on 10/2/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #2404 Tank label weathered and not legible.



Photo #2405 Multiple places with debris and weeds on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #2406 Multiple places with debris and weeds on location.



Photo #1977 from #699801876 inspection conducted on 10/2/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #2407 Secondary containment not adequate weeds and debris inside tank containment.



Photo #2408 Rutting occurring on location due to lack of stabilization.