

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: red AG fencing around wellheads, and ECD's, 4' barb wire around production equipment and tanks

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Ancillary equipment	# 1			
Comment:	automation			
Corrective Action:				Date: _____
Type: Bird Protectors	#			
Comment:				
Corrective Action:				Date: _____
Type: Bradenhead	# 2			
Comment:				
Corrective Action:				Date: _____
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date: _____
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date: _____
Type: Emission Control Device	# 2			
Comment:				
Corrective Action:				Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date: _____

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shares containment with oil tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 251085 Type: WELL API Number: 123-18888 Status: SI Insp. Status: SI

Facility ID: 284091 Type: WELL API Number: 123-23748 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Annual bradenhead test is not current. Contact COGCC engineering. 12/18/2020

Corrective Action: Comply with 341 c. Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 12/8/2020 at approximately 1215 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Kirby 33-36 Company Name- PDC energy API- 05-123-18888 In Weld County Colorado. While there, I observed TA well. During this inspection the following possible compliance issues were observed: Annual bradenhead test is not current. Contact COGCC engineering. Comply with 341 c. 12/18/20 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	12/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501993	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306775