

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/08/2020

Submitted Date:

12/09/2020

Document Number:

696202098

FIELD INSPECTION FORM

Loc ID 335091 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335091	LOCATION	AC			-	CC 0629-23-42 Pad	RI

General Comment:

On 12/08/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Laramie Energy's CC 0629-23-42 location in Garfield County, Colorado.

This inspection is a follow up to #696201173 to document compliance for the following corrective actions:
1002.f: Install or repair required BMPs per Rule 1002.f.(2)C

It was observed that Location remains out of compliance with corrective actions and 1002.f Rules.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 335091 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: FIR #696201173 documented insufficient BMPs to stabilize and protect cut slopes of the Location. Operator was required to comply with Rule 1002.f.(2)C.

It was observed in this inspection that BMPs to stabilize and protect cut slopes have not been installed. Corrective action has not been addressed and remains applicable.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C and in accordance with good engineering practices; ensure BMPs are maintained in proper functioning condition to stabilize soils and to allow for proper sediment laden-free stormwater discharge from the Location; Continue to conduct stormwater management in accordance with Rule 1002.f until location receives a passing final reclamation inspection.

Date: 04/28/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202099	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306949