

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2020

Submitted Date:

12/03/2020

Document Number:

700701974**FIELD INSPECTION FORM**

Loc ID 335547	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>950 17TH STREET, SUITE 1900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 9 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289971	WELL	PR	09/01/2020	GW	045-13927	GENTRY E1	PR
290735	WELL	PR	08/01/2020	GW	045-14191	GENTRY E6	PR
290736	WELL	PR	09/01/2020	GW	045-14190	GENTRY E8	PR
295316	WELL	XX	04/02/2018	LO	045-15717	Gentry E9	XX
295318	WELL	XX	04/02/2018	LO	045-15718	Gentry E11	XX
295322	WELL	XX	04/02/2018	LO	045-15719	Gentry E7	XX
295662	WELL	XX	04/02/2018	LO	045-15803	Gentry E5	XX

General Comment:**COGCC Inspection Report Summary**

On Wednesday 12/3/20 at approximately 1030, I, Inspector Scott Ramsey, conducted a routine inspection at URSA Gentry E, at Location # 335547 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking

- Cut slope behind tank battery is eroding and needs stabilization

- No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 3		corrective date
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST		,	
Comment:	shared containment with condensate tanks					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	289971	Type:	WELL	API Number: 045-13927 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	290735	Type:	WELL	API Number: 045-14191 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	290736	Type:	WELL	API Number: 045-14190 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	295316	Type:	WELL	API Number: 045-15717 Status: XX Insp. Status: XX
Facility ID:	295318	Type:	WELL	API Number: 045-15718 Status: XX Insp. Status: XX
Facility ID:	295322	Type:	WELL	API Number: 045-15719 Status: XX Insp. Status: XX
Facility ID:	295662	Type:	WELL	API Number: 045-15803 Status: XX Insp. Status: XX

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
		Ditches				

Comment: • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance which in turn can lead to tracking
 • Cut slope behind tank battery is eroding and needs stabilization
 • No evidence of tracking control BMP's

Corrective Action: maintain all BMP's
 Provide proof of tracking control BMP's

Date: 01/07/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402546276	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302813
700701981	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302800