

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2020

Submitted Date:

12/03/2020

Document Number:

700701976

FIELD INSPECTION FORM

Loc ID 335551 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 950 17TH STREET, SUITE 1900
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293336	WELL	PR	10/01/2017	GW	045-14947	DEVER C9	PR
293337	WELL	PR	11/06/2007	GW	045-14946	DEVER C8	PR
293338	WELL	PR	08/01/2020	GW	045-14945	Dever C7	PR
293341	WELL	PR	09/01/2020	GW	045-14942	DEVER C4	PR
293342	WELL	PR	09/01/2020	GW	045-14941	DEVER C3	PR
293343	WELL	XX	03/12/2018	LO	045-14940	Dever C2	XX

General Comment:

[COGCC Inspection Report Summary](#)
On Wednesday 12/3/20 at approximately 1330, I, Inspector Scott Ramsey, conducted a routine inspection at URSA Dever C, at Location # 335551 in Garfield county Colorado.
While there, I observed normal production operations. All meters have been calibrated on location within the past year.
During this inspection the following possible compliance issues were observed:
• Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking
• No evidence of tracking control BMP's
Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type:	Bird Protectors	# 6	corrective date
Comment:			
Corrective Action:			Date:
Type:	Gas Meter Run	# 5	
Comment:	All meters have been calibrated on location within the past year.		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:	one (1) tank is heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		,
Comment:	shared containment with condensate tanks				
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	293336	Type:	WELL	API Number:	045-14947	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293337	Type:	WELL	API Number:	045-14946	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293338	Type:	WELL	API Number:	045-14945	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293341	Type:	WELL	API Number:	045-14942	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293342	Type:	WELL	API Number:	045-14941	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293343	Type:	WELL	API Number:	045-14940	Status:	XX	Insp. Status:	XX

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms		Culverts				

Comment:
 • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance which in turn can lead to tracking
 • No evidence of tracking control BMP's

Corrective Action:
 Maintain all BMP'S
 Provide proof of tracking control BMP's

Date: 01/07/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402546278	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302815
700701983	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302802