

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2020

Submitted Date:

12/10/2020

Document Number:

701100875

FIELD INSPECTION FORMLoc ID 311561 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210811	WELL	PR	09/16/1989	GW	045-06569	CHEVRON MV-35-29	PR
282831	WELL	PR	06/11/2006	GW	045-11852	CHEVRON GM 432-29	PR
282832	WELL	PR	06/20/2006	GW	045-11851	CHEVRON GM 331-29	PR
282833	WELL	PR	05/09/2006	GW	045-11850	CHEVRON GM 431-29	PR
282834	WELL	PR	06/16/2006	GW	045-11849	CHEVRON GM 531-29	PR

General Comment:**COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W 29NWNE, Location ID: 311561 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

GM 331-29 well sign is not installed.

Equipment and materials stored on location.

Unmarked deadman.

Ditch behind tank battery and separators has sediment build up. Checkdam behind tank battery is washed out and needs maintained.

Ditch along road running through location has dirt pile blocking flow. Ditch has rut damage. Surface areas around wells and tank battery is rutted. No BMPs around well head CHEVRON # MV-35-29. Location looks to have expanded.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	GM 331-29 well sign is not installed.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	01/11/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Equipment and materials stored on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/11/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 5	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 5	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 1	
Comment:	Unmarked deadman.	
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date: 12/26/2020

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					
Corrective Action:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210811 Type: WELL API Number: 045-06569 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 282831 Type: WELL API Number: 045-11852 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 282832 Type: WELL API Number: 045-11851 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 282833 Type: WELL API Number: 045-11850 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 282834 Type: WELL API Number: 045-11849 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Fail					
Check Dams	Fail					

Comment: Ditch behind tank battery and separators has sediment build up. Checkdam behind tank battery is washed out and needs maintained. Ditch along road running through location has dirt pile blocking flow. Ditch has rut damage. Surface areas around wells and tank battery is rutted. No BMPs around well head CHEVRON # MV-35-29. Location looks to have expanded.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/26/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701100876	Inspection 701100875 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308445