

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2020

Submitted Date:

12/14/2020

Document Number:

700702023**FIELD INSPECTION FORM**Loc ID 335127 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287515	WELL	PR	12/10/2008	GW	045-12998	PLATZER 33D-27-692	PR
287516	WELL	PR	12/10/2008	GW	045-12997	PLATZER 33B-27-692	PR
287517	WELL	PR	03/07/2007	GW	045-12996	PLATZER FEDERAL 43B-27-692	PR
287518	WELL	PR	03/16/2007	GW	045-12995	PLATZER FEDERAL 43D-27-692	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 12/14/20 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Platzer, at Location # 335127 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. Limited storm water inspection due to snow.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking

- No evidence of tracking control BMP's

- Debris/unused equipment next to combustor

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:	snow covered		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	• Debris/unused equipment next to combustor		
Corrective Action:	remove debris/unused equipment	Date:	01/14/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	
Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	

Equipment:

				corrective date
Type: Bradenhead	# 4			
Comment:	Braden heads have a port for manual gauge monitoring			
Corrective Action:				Date:
Type: Bird Protectors	# 4			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	one (1) chemical tank at well heads and one (1) 500 gallon methanol tank at separators			
Corrective Action:				Date:
Type: Gas Meter Run	# 4			
Comment:	All meters have been calibrated on location within the past year.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 4			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 4			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLS	STEEL AST		,	
Comment:	one (1) tank is heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Ramsey, Scott

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	287515	Type:	WELL	API Number:	045-12998	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287516	Type:	WELL	API Number:	045-12997	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287517	Type:	WELL	API Number:	045-12996	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287518	Type:	WELL	API Number:	045-12995	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
Ditches						
Berms		Culverts				
Sediment Traps						
Culverts		Ditches				

Comment: Limited storm water inspection due to snow.
 • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance which in turn can lead to tracking
 • No evidence of tracking control BMP's

Corrective Action: Maintain ALL BMP's
 Provide proof of tracking control BMP's

Date: 01/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702026	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310062