

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2020

Submitted Date:

12/08/2020

Document Number:

697601110**FIELD INSPECTION FORM**Loc ID 317866 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240088	WELL	PR	08/01/2019	OW	123-07876	PREMIUM TURKEY FARMS C 1	EI

General Comment:

[wellhead location only inspected in this report.](#)
[Centralized battery for three wells including this one inspected separately](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	2nd wellhead sign incorrectly identifying AMOCO as operator Sign information inaccurate at well(s) or battery		
Corrective Action:	remove Amoco sign to comply with Rule 210.b.	Date:	03/08/2021

Emergency Contact Number:	
Comment:	adequate
Corrective Action:	
Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	see attached photo of weed buildup around and in working zones of pumpjack		
Corrective Action:	Comply with Rule 603.f .	Date:	12/22/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: no spills observed at surface around pumpjack

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	electric boxes		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 240088 Type: WELL API Number: 123-07876 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402549281	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305938
697601111	weeds in pumjack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305936
697601112	sign and sign identifying incorrect operator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305937