

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/07/2020

Submitted Date:

12/08/2020

Document Number:

700404461

**FIELD INSPECTION FORM**

Loc ID 316441 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Thompson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274580	WELL	PA	10/22/2019	GW	103-10536	Federal 299-23-3	PA

**General Comment:**

A routine inspection identified the following compliance issues:  
 1) Remove unused riser, panel, deadman, pole, and sign. Photos 1, 4, 5, 6. Complete by 3-8-2021.  
 This is a summary of inspection report 700404461.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER				
Comment:	Lease road entrance.				
Corrective Action:				Date:	

**Emergency Contact Number:**

Comment:	911			Date:	
Corrective Action:				Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT				
Comment:	Remove all equipment from location including the riser and lease road sign.				
Corrective Action:	Comply with Rule 603.f .			Date:	03/08/2021

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 1				
Comment:	Riser.				
Corrective Action:				Date:	
Type: Other	# 2				
Comment:	Pole near location entrance & panel next to riser.				
Corrective Action:				Date:	

**Venting:**

Yes/No				Date:	
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 274580 Type: WELL API Number: 103-10536 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402548988	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305694">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305694</a>
700404462	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305689</a>