

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2020

Submitted Date:

12/08/2020

Document Number:

700701988

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection ☐
 335300 Ramsey, Scott 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264260	WELL	PR	07/27/2016	GW	045-08134	BRYNILDSON 14C - 20 - 692	PR
276111	WELL	PR	02/13/2012	GW	045-10428	BRYNILDSON 14B-20-692	PR
276112	WELL	PR	07/28/2009	GW	045-10427	BRYNILDSON 13A-20-692	PR
276113	WELL	PR	06/08/2009	GW	045-10426	BRYNILDSON 14D-20-692	PR
298340	WELL	PR	06/04/2009	GW	045-17144	BRYNILDSON 24C-20-692	PR
298341	WELL	PR	06/08/2009	GW	045-17145	BRYNILDSON 24B-20-692	PR
298342	WELL	PR	06/03/2009	GW	045-17146	BRYNILDSON 14A-20-692	PR
298343	WELL	PR	06/08/2009	GW	045-17147	BRYNILDSON 24A-20-692	PR
298344	WELL	PR	06/08/2009	GW	045-17148	BRYNILDSON 23A-20-692	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 12/8/20 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Brynildson 14C, at Location # 335300 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance
- No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Type	IGNITOR/COMBUSTOR			
Comment:				
Corrective Action:			Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 9		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 9		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	500 BBLs	STEEL AST		,	
Comment:	two (2) tanks ARE heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	264260	Type:	WELL	API Number:	045-08134	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	276111	Type:	WELL	API Number:	045-10428	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	276112	Type:	WELL	API Number:	045-10427	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	276113	Type:	WELL	API Number:	045-10426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298340	Type:	WELL	API Number:	045-17144	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298341	Type:	WELL	API Number:	045-17145	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298342	Type:	WELL	API Number:	045-17146	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298343	Type:	WELL	API Number:	045-17147	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms		Culverts				
Sediment Traps						
Rip Rap		Ditches				

Comment: • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
BMP's require maintenance
• No evidence of tracking control BMP's

Corrective Action: Maintain ALL BMP's
Provide proof of tracking control BMP's

Date: 01/08/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402549402	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306070
700701992	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306064