

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2020

Submitted Date:

12/07/2020

Document Number:

701100857**FIELD INSPECTION FORM**Loc ID 334113 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292775	WELL	PR	04/30/2008	GW	045-14748	BOSELY SG 44/27	PR
293568	WELL	PR	11/19/2007	GW	045-15052	BOSLEY SG 344-27	PR
293569	WELL	PR	11/20/2007	GW	045-15054	BOSELY SG 341-34	PR
293570	WELL	PR	01/31/2009	GW	045-15055	BOSELY SG 41-34	PR
293571	WELL	PR	11/20/2007	GW	045-15056	BOSELY SG 544-27	PR
293572	WELL	PR	11/20/2007	GW	045-15057	BOSELY SG 541-34	PR
293574	WELL	PR	11/20/2007	GW	045-15053	BOSELY SG 441-34	PR
293579	WELL	PR	11/20/2007	GW	045-15058	BOSELY SG 444-27	PR

**General Comment:****COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at TEP ROCKY MOUNTAIN LLC, BOSELY-67S96W 27SESE, Location ID: 334113 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Capacities are not filled out on tanks.

Berm around location is breached in several areas. Ditch around location not maintained. Location is deeply rutted.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Capacities are not filled out on tanks.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	03/08/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	292775	Type:	WELL	API Number:	045-14748	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293568	Type:	WELL	API Number:	045-15052	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293569	Type:	WELL	API Number:	045-15054	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293570	Type:	WELL	API Number:	045-15055	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293571	Type:	WELL	API Number:	045-15056	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293572	Type:	WELL	API Number:	045-15057	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293574	Type:	WELL	API Number:	045-15053	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293579	Type:	WELL	API Number:	045-15058	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Fail					
				Vehicle Tracking	Fail	
		Compaction	Pass			
Ditches	Fail					
Compaction	Fail					

Comment: Berm around location is breached in several areas. Ditch around location not maintained. Location is deeply rutted.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/22/2020

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402548661	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305435">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305435</a>
701100858	Inspection 701100857 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305432">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305432</a>