

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2020

Submitted Date:

12/15/2020

Document Number:

696302754**FIELD INSPECTION FORM**Loc ID 420168 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 LINCOLN STREET SUITE 4700City: DENVER State: CO Zip: 80290**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	Eastern Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420173	WELL	SI	11/01/2018	OW	123-32488	Chalk Bluffs 36-13H	TA

General Comment:[Follow-Up Inspection to FIR 696301536 dated 03.10.2020.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Well appears to have been Plugged and Abandoned per Form 42 PA Notice #402505514 dated 10.08.2020. All Surface Production to be removed 90 days after plugging.		
Corrective Action:	Comply with Rule 603.f. and 1004.a	Date:	01/15/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

corrective date

Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		

Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLS	STEEL AST		40.791320,-104.046060
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspected FacilitiesFacility ID: 420173 Type: WELL API Number: 123-32488 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Well appears to have been Plugged and Abandoned per Form 6 #402350543 approved on 10.08.2020. Form 42 PA Notice #402505514 dated 10.08.2020 for Plugging Operations to start on 10.10.2020.
Appears No Form 6 Subsequent is file or in Review file.
Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, will be filed with the Director. The abandonment details will include an account of the manner in which the abandonment or plugging work was performed.

Corrective Action: Submit Form 6S to COGCC Engineering DepartmentDate: 01/15/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 12/09/2020 at approximately 13:58 I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Whiting Oil and Gas Corp. Chalk Bluff 36-13H , Location ID #420168 in Weld County, Colorado.</p> <p>While there, I observed Production Operations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Well appears to have been Plugged and Abandoned per Form 6 #402350543 approved on 10.08.2020. Form 42 PA Notice #402505514 dated 10.08.2020 for Plugging Operations to start on 10.10.2020.</p> <p>Appears No Form 6 Subsequent is file or in Review file.</p> <p>Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, will be filed with the Director. The abandonment details will include an account of the manner in which the abandonment or plugging work was performed.</p> <p>Submit Form 6S to COGCC Engineering Department. Corrective Action Date 01.15.2021</p> <p>All Production Equipment to be Removed for Final Reclamation. Per Rule 1004.a. Corrective Action Date 01.15.2021. (Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.)</p> <p>Unused Workover Rig Equipment. See photos. Comply with Rule 603.f. Corrective Action date 01.15.2021</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	12/14/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302755	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310315