


To Emily Waldron,

We have been working to correct the lack of bradenhead pressure measurement per 689805026 (Rodewald 43-5), 689805024 (Federal 1-43-32), 689805022 (Iverson 32-5), 689805028 (Rodewald 11-4), and 689805020 (Federal 1-33-7) submitted to North Shore E&P on 11/20/2020 after your 11/18/2020 inspection. We have identified how the bradenhead pressure measurement can be accomplished and installed at each well, and have purchased materials to do so. The bradenhead pressure measurement device has been installed on the Federal 1-33-7 well. See photo below. This process to install was not simple by any means due to a significant frost layer. We are requesting an extension to install the other gauges for the Rodewald 43-5, Federal 1-43-32, Iverson 32-5, & Rodewald 11-4 in the spring due to the frost layer. Please let us know if this will be possible.



Best Regards,



Mark Fordney, P.E.,PMP, Manager of Facilities Engineering  
North Shore Exploration & Production, LLC  
(720) 636-1472  
mark@northshoreenergyllc.com