

Inspection Photos
Operator: Simcoe
API: 067-09579
Date: 12/15/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is largely snow covered and can be observed in a grazed condition beneath snow.



Photo 3. View of metal tube within the western project area.



Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush understory. Additional understory grasses and forbs are not observable due to snow cover.