

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2020

Submitted Date:

12/16/2020

Document Number:

699303124**FIELD INSPECTION FORM**

Loc ID 333302 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239920	WELL	PR	01/01/2019	OW	123-07708	VONASEK 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil under load out line on east crude oil tank		
Corrective Action:	Comply with Rule 907.e	Date:	06/04/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	fabricated square tubing		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	bird protector has fallen off and is lying next to separator		
Corrective Action:	Comply with Rule 605.b (7)	Date:	06/20/2020
Type: Gas Meter Run	# 1		
Comment:	card in meter box does not indicate current calibration		
Corrective Action:		Date:	

Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 239920 Type: WELL API Number: 123-07708 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: braden head test is over 1 year and needs to be done annually

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 12/16/2020 at approximately 1215 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location.</p> <p>Vonasek # 1 at API #05-123-07708 in Weld County Colorado.</p> <p>While there, I observed a producing wellsite and tank battery. Follow up inspection per Doc # 699301773.</p> <p>During this inspection the following possible compliance issues were observed and are now delinquent:</p> <p>907.e housekeeping: Stained soil at load out line on the East Crude oil tank, CA date 6-4-2020</p> <p>See attached photos 1 & 2.</p> <p>605.b(7) wild life screen: Bird protector has fallen off of Horizontal Heated Separator stack and is lying on the ground, CA date 6-20-2020 see attached photos 3 & 4.</p> <p>Location: snow covered, Weather: clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	12/16/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303125	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5311686