

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2020

Submitted Date:

12/16/2020

Document Number:

700404588

**FIELD INSPECTION FORM**

Loc ID 336550 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10342  
Name of Operator: WOODARD\* SANDRA K  
Address: 602 OURAY AVENUE  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,	970-261-6589	3oilwells@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229623	WELL	SI	06/01/2019	OW	103-07280	STAGNER RECTOR 7	SI

**General Comment:**

A follow up inspection of documents:

- 1) FIR 679705374 dated 9-6-2019.
- 2) FIR 700400162 dated 2-24-2020.
- 3) FIR 700401505 dated 5-15-2020.
- 5) FIR 700402579 dated 7-24-2020.
- 6) NOAV 402462164 dated 8-7-2020.

The following compliance issues are uncompleted:

- 1) Stained & oily soil around pump jack. Photo 3. Complete by 10-9-2019.
- 2) Open bucket of fluid next to well head. Photo 4. Complete by 10-9-2019.

This is a summary of inspection report 700404588.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Open bucket of fluid next to well head. Bucket without wildlife protection & could be tipped over.  Stained soil around well head and flow line.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Partial fencing.		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Casing open to atmosphere.		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 229623 Type: WELL API Number: 103-07280 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

